

New Service Cam Bearings For Gen IV V8 Engines

2005-2007 Buick Rainier

2007-2013 Cadillac CTS-V

2007-2013 Cadillac Escalade, Escalade ESV, Escalade EXT

2006-2007 Chevrolet Monte Carlo SS

2006-2009 Chevrolet Impala SS

2007-2009 Chevrolet TrailBlazer SS

2007-2013 Chevrolet Avalanche, Silverado 1500, Suburban, Tahoe

2007-2013 Chevrolet Express

2008-2013 Chevrolet Corvette, Corvette Grand Sport, Corvette ZR1, Z06

2009-2012 Chevrolet Colorado

2010-2013 Chevrolet Camaro

2007-2009 GMC Envoy

2007-2013 GMC Sierra 1500, Sierra Denali, Yukon, Yukon XL, Yukon Denali, Yukon Denali XL

2007-2013 GMC Savana

2009-2012 GMC Canyon

2006-2008 Pontiac Grand Prix, GXP

2008-2009 Pontiac G8 GT

Equipped with Gen IV V8 Engine Except Hybrid (LFA, LZ1)

This bulletin replaces PIP5014. Please discard PIP5014.



New service cam bearings for Gen IV V8 engines have been released.

When replacing cam bearings, replace all five cam bearings with the newly released service parts. The new cam bearings have a polymer coating and will appear different. The bearing surface looks black due to the coating.

Note

If the black coating wears off, it does not mean that the bearing is bad. There is still a lead lining material underneath. If the lining is damaged or worn beyond specifications, then replacement would be required.

The maximum cam journal to bearing oil clearance of 0.005 inch (0.127 mm) with the service bearings installed on engines with AFM or CMP.

The maximum cam journal to bearing oil clearance of 0.006 inch (0.152 mm) with the service bearings installed on engines without AFM or CMP.

First Design Camshaft with Aluminum Blocks and Iron Blocks up to early 2009

Part Number	Description
19260874	Replaces P/N 19167383 – Position #1 and #5 2005-2013 Gen IV Engines with Aluminum Block 2007-2009 Gen IV Engines with Iron Block and First design Camshaft
19260875	Replaces P/N 19167382 – Position #2 and #4

	2005-2013 Gen IV Engines with Aluminum Block
	2007-2009 Gen IV Engines with Iron Block and First Design Camshaft
19260876	Replaces P/N 19167218 Position #3
	2005-2009 Gen IV Engines with Aluminum Block
	2007-2009 Gen IV Engines with Iron Block and First Design Camshaft

Second Design Camshaft with Iron Block Only Late 2009 to Present

Part Number	Description
19260877	Replaces P/N 19167383 Position #1 and #5
	2009 1/2-2013 Gen IV Engines with Iron Block and Second Design Camshaft
19260878	Replaces P/N 19167382 Position #2 and #4
	2009 1/2-2013 Gen IV Engines with Iron Block and Second Design Camshaft
19260879	Replaces P/N 19167218 Position #3
	2009 1/2-2013 Gen IV Engines with Iron Block and Second Design Camshaft

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J0846	Camshaft Bearing Replacement	Use Published Labor Operation Time