

Diagnostic Tip: VIS / GWM / IVH May Not Match Actual Audio System of Vehicle

2013 Chevrolet Malibu Hybrid

with RPO UFU

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

In some cases, it may be found that some GM computer systems (IVH / VIS / GWM, etc.) do not properly show the correct audio system of the vehicle. Some 2013 Malibu's were built with RPO AUI but this RPO does not display in IVH / VIS / GWM, etc.

Recommendation/Instructions

Please refer to the vehicle VIN if the seventh VIN digit is an R, then the vehicle was built with RPO AUI.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.